



# MAC Motor | JCM Control box

## Connections


- ① | 1. Connect cables 1, 2, 3, 4 and 5 to the corresponding limit switch terminals.



- ② | 2. Final control board wiring diagram.



- ③ | 3. Image showing the final control board connections.






## Programming procedures

- ① | 1. Remote control / transmitter programming



- ② | 2. Manual travel limit programming



Assembly  
manual  
MAC Motor

